To: Mylott, Richard[Mylott.Richard@epa.gov]; Griswold, Hays[Griswold.Hays@epa.gov]

Cc: McClain-Vanderpool, Lisa[Mcclain-Vanderpool.Lisa@epa.gov]

From: Ostrander, David

Sent: Mon 8/24/2015 6:28:14 PM

Subject: RE: Q on Colorado DRMS presence at GKM on August 5

I'll let Hays respond, but my understanding was they were there before the incident happened and had left just prior to check on another site.

From: Mylott, Richard

Sent: Monday, August 24, 2015 12:14 PM To: Griswold, Hays; Ostrander, David

Cc: McClain-Vanderpool, Lisa

Subject: Q on Colorado DRMS presence at GKM on August 5

I'm looking through the media tracking sheet and see there are some old questions regarding who was physically working at the Gold King Mine site on August 5. I believe there is a general answer on the GKM website that states EPA, our contractor, and Colorado DRMS staff were present, but, in case this question persists, I wanted to confirm whether DRMS staff were physically present at the entrance or in the mine adit that day.

This is not for external use at this point, but can you clarify? Do we have pictures that confirm Colorado DRMS role and presence in site activity that day?

Rich x 6654